PROJECT

Follow-Up Gutter Repairs Beside Solar Panels in Cirencester

Location:
Cirencester, Gloucestershire

Roof Type / System:
Profiled metal roof with valley gutter and adjacent solar panels

Project Date / Year:
2026



Project photograph

PROJECT OVERVIEW

Following gutter repairs at a machining business in Cirencester, Elite Waterproofing returned to carry out further work on a separate gutter at the same site. This gutter runs between the profiled metal roof and a rooftop solar panel array, so the repair work was focused on the gutter channel and its junction with the adjoining roof areas.

THE CHALLENGE

A second gutter required attention alongside the solar panel array. The work needed to be carried out in the narrow area between the panels and the profiled roof, with care around the existing roof and solar installation.

SURVEY & ASSESSMENT

The follow-up work focused on a separate gutter run beside the solar panels. The gutter channel

and its interfaces with the adjoining roof sheets required targeted attention.

PROPOSED SOLUTION

Carry out targeted repair work to the second gutter, working alongside the solar panels and adjoining profiled metal roof.

WORKS UNDERTAKEN

Completed further gutter repair works along the channel beside the solar array, treating the gutter area shown in the project photographs.

PROJECT OUTCOME

A second gutter at the Cirencester site received follow-up repair work, extending the gutter repairs beyond the area addressed during the initial project.

PROJECT PHOTOGRAPHY



Cirencester Valley Gutter Repair Detail

ELITE WATERPROOFING

For project enquiries visit elitewaterproofing.co.uk