PROJECT

Emergency Asbestos Roof Sheet Repair in Armthorpe, Doncaster

Location:
Armthorpe, Doncaster

Roof Type / System:
Corrugated asbestos roof sheet — localised patch repair

Project Date / Year:
September 2026



Project photograph

PROJECT OVERVIEW

A machinery malfunction sent a steel rod through the roof of a building in Armthorpe. Thankfully, nobody was injured, but the impact damaged an asbestos roof sheet. After HSE visits, the affected section of the building remained closed while the roof damage was addressed.

The client contacted Elite Waterproofing for an urgent repair. We were on site three days after the enquiry and completed the localised patch repair in less than a day. The work dealt with the damaged area quickly, helping the client move towards getting the section back into use.

THE CHALLENGE

A steel rod had punctured and cracked a corrugated asbestos roof sheet. The affected part of the building had been closed off pending repair, so the client needed a prompt solution.

SURVEY & ASSESSMENT

The reported damage was to a localised section of the corrugated roof sheet. The photos show the damaged opening and the completed repair. No wider roof area or additional repair requirements have been specified.

PROPOSED SOLUTION

Carry out a localised patch repair to the damaged roof sheet, addressing the opening while keeping the scope focused on the affected area.

WORKS UNDERTAKEN

Elite Waterproofing attended three days after receiving the enquiry and completed a patch repair to the damaged section. The repair took less than one day.

PROJECT OUTCOME

The damaged section received a localised repair in under a day. The urgent work addressed one of the outstanding roof issues affecting the closed-off area. No formal HSE sign-off or reopening date has been provided.

PROJECT PHOTOGRAPHY



Completed Asbestos Roof Patch Repair



Close-Up of Roof Sheet Patch Repair

ELITE WATERPROOFING

For project enquiries visit elitewaterproofing.co.uk